


Irrigation tanks' storage

District  No of tanks  Tanks filled up (100%)



TOTAL

 14,138  2,707


Tamil Nadu District Average water level below ground level

August - September 2017 in Mts


S.No.	District	Aug-17	Sep-17	Rise / Fall
1	Thiruvannamalai	9.89	5.97	3.92
2	Perambalur	13.4	10.2	3.20
3	Villupuram	10.16	7.92	2.24
4	Namakkal	15.72	13.83	1.89
5	Nagapattinam	6.41	4.98	1.43
6	Karur	8.84	7.47	1.37
7	Vellore	10.26	8.98	1.28
8	Virudhunagar	11.34	10.18	1.16
9	Dharmapuri	11.87	10.79	1.08
10	Salem	13.94	12.89	1.05
11	Thiruppur	15.16	14.29	0.87
12	Madurai	9.41	8.6	0.81
13	Theni	12.49	11.7	0.79
14	Trichy	13.59	12.88	0.71
15	Thiruvallur	6.53	5.86	0.67
16	Cuddalore	7.79	7.23	0.56
17	Kanchipuram	5.45	4.91	0.54
18	Krishnagiri	9.81	9.29	0.52
19	Thanjavur	4.19	3.68	0.51
20	Ariyalur	6.05	5.67	0.38
21	Ramanathapuram	6.03	5.72	0.31
22	Coimbatore	18.02	17.72	0.30
23	Kanyakumari	8.78	8.52	0.26
24	Erode	13.17	12.97	0.20
25	Pudukkottai	9.52	9.33	0.19
26	Sivagangai	9.92	9.77	0.15
27	Thoothukudi	8.8	8.67	0.13
28	Nilgiris	2.64	2.51	0.13
29	Tirunelveli	10.69	10.66	0.03
30	Thiruvarur	5.31	5.38	-0.07
31	Dindigul	12.23	12.41	-0.18

Legend	Ground water Improved
	Ground water has fallen


TEYNAMPET



KODAMBAKKAM




VALASARAVAKKAM




ALANDUR



ADYAR



PERUNGUDI



SHOLINGANALLUR




■ September ■ October

(Figures: Water level in metres from ground level)

City's Water Table Depth Has Nearly Doubled Since '00

Water table at lowest depth in these villages (2022 survey)

(Below ground, in metres)



How Gurgaon's water table has fallen in 50 years

YEAR

Average water level (below ground, in metres)

1974

6.64

2006

19.85

2014

26.3

2018

33.23

2019

35.8

2020

36.2

2021

36.5

As the authorities are taking to restore water levels


EQUIPMENT FOR MONITORING

Installation of water meters in villages to measure groundwater level as well as other equipment to capture rainwater

REVAMP | Renovation of water bodies in villages to restore the water table


WATER PLAN | Formulation and implementation of village-level 'water security' plan for conservation of water

STRICTS IN DIP IN WATER TABLE



ZONE	JULY	AUGUST	DIFFERENCE
Tiruvottiyur	4.68	4.77	-.09
Manali	4.38	4.40	-.02
Madhavaram	5.69	5.97	-.28
Tondiarpet	6.39	6.55	-.16
Royapuram	6.62	6.79	-.17
Thiru Vi Ka Nagar	6.42	6.76	-.34
Ambattur	7.27	7.42	-.15
Anna Nagar	4.94	4.83	+.11
Teynampet	4.92	4.98	-.06
Kodambakkam	4.95	5.40	-.45
Valasaravakkam	5.78	5.71	+.07
Alandur	4.75	4.69	+.06
Adyar	4.37	4.20	+.17
Perungudi	3.84	4.12	-.28
Shollinganallur	3.20	2.88	+.32


(Water level in metres below ground level)



WATER-TABLE


Groundwater level (In metres) as on February 2023

District □ February 2022 ■ February 2023 ▲ Rise ▼ Fall




SAFE

409 firkas



**SALINE/ POOR
QUALITY**

34 firkas



(Source: A government order issued by the state public works department on October 28, 2021)

October November
Rise Fall

3.21 2.22 0.99 Nil

Tiruvallur

2.16 1.59 0.57 Nil

Kancheepuram

4.12 4.34 Nil 0.22

Vellore

3.22 2.43 0.79 Nil

Tiruvannamalai

5.11 4.03 1.08 Nil

Dharmapuri

2.36 2.39 Nil 0.03

Krishnagiri

4.38 3.17 1.21 Nil

Cuddalore

5.03 3.89 1.14 Nil

Villupuram

1.93 1.58 0.35 Nil

Thanjavur

2.17 1.73 0.44 Nil

Tiruvallur

4.27 4.27 0 0

Erode

10.59 10.24 0.35 Nil

Coimbatore

7.35 6.39 0.96 Nil

Tiruppur

1.96 1.98 Nil 0.22

The Nilgiris

5.91 4.82 1.09 Nil

Dindigul

5.15 4.01 1.14 Nil

Madurai

7.92 4.07 3.85 Nil

Ramanathapuram

3.43 2.45 0.98 Nil

Sivagangai

6.25 4.16 2.09 Nil

Theni

4.93 4.28 0.65 Nil

Thoothukudi